Foster Family Home - Corrective Action Report

Provider ID:

1-190024

Home Name:

Maria Fe McGehee, RN

Review ID:

1-190024-1

47-500A Waipahu Street

Reviewer:

Angel England

Kaneohe

HI 96744

Begin Date:

4/3/2019

Foster Family Home

Required Certificate

[11-800-6]

6.(d)(1)

Comply with all applicable requirements in this chapter; and

Comment:

6.d.1 Home inspection for a 2 bed new home application. Corrective action report issued during visit with a written plan of correction due to CTA by April 26, 2019.

Foster Family Home

Personnel and Staffing

[11-800-41]

41.(b)(8)

Have documentation of current training in blood borne pathogen and infection control, cardiopulmonary

resuscitation, and basic first aid.

Comment:

41.b.8 CG#2 completed CPR/1st aid online which is not an authorized process for completion.

Foster	Family	Home
--------	--------	------

Physical Environment

[11-800-49]

Bathrooms with non-slip surfaces in the tubs and or showers, and toilets adjacent or easily accessible to sleeping 49.(a)(1) 49.(a)(2) Grab bars in bath and toilet rooms used by the client, as appropriate; 49.(a)(6) A means of unobstructed travel from the client's bedroom to the outside of the dwelling at street or ground level.

Comment:

49.a.1 There is no non-slip surface present in shower.

49.a.2 There are no grab bars present around toilet area.

49.a.6 There is a step out of the home and a step up to the carport (ground level). The home's ramps do not meet gradient slope requirements and are steep.

Primary Care G

Community Care Foster Family Home (CCFFH) Written Plan of Correction for Deficiencies Listed in Corrective Action Report Chapter 17-1454

CCFFH Name:

Maria Fe McGehee

CCFFH Address: 47-500A Waipaipai St. Kaneohe, Hi 96744

Rule Number	Corrective Action Taken	Date Corrected	Prevention Strategy	
41.b.8	CG#2 completed CPR/1st aid in class.	4/22/19	In the future, CPR/1st aid training will be taken via class in person and not online.	
49.a.1	Applied non-slip surface in the shower.	4/22/18	Keep a non-slip surface in the shower.	
49.a.2	Installed grab bars around toilet area.	4/22/19	Keep grab bars around toilet area.	
19.a.6 Reconstructed ramp by carport (ground level) to meet code requirements as recommended by a Contractor.		4/22/19	Keep ramps that meet code requirements installed.	
			Control of the Contro	

Primary Caregiver's Signature:				
Print Name: MARIA FE	MCGENEE	Date of Signature:	4/22/19	